UNITED STATES ENVIRONMENTAL PROTECTION AGENCY REGION 1 BOSTON, MASSACHUSETTS



	US EPA On-Scene Coordinator: OHM Corporation Response Manager				American Glue & Resin Site, Middleton,MA Contract # 68-R1-98-01 Order # 0011				
			Week of: 7 February - 1	3 February 1999					
	WORK TO BE PERFORMED:		Sunday (NO WORK)		Superfund Records Center American Glue &				
a.	WORK TO BE PERIORMED.	d.			1 A 1 B				
u .					1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1				
b.		e.		t ja ki serki sa stepa ki keta saja Kapangangangan	594145				
c.		f.							
	AUTHORIZED PERSONNEL:		AUTHORIZED EQUIPMENT:		IT SUBCONTRACTORS ON-SITE				
	AUTHORIZED PERSONNEL.		AOTTORIZED EGGI METT.	POV- 1					
	RT-			Van-					
	PA-			truck-					
	Operator-			copier- 1					
	Foreman-			water cooler- 1					
				fax machine- 1					
				uniloader-					
			Monday						
a.	WORK TO BE PERFORMED: Continue drum sampling and overpacking.	d.							
b.	Perform HazCating on samples collected.	e.							
ν.	, one thin, take a single or property and the si								
C.		f.							
	AUTHORIZED PERSONNEL:		AUTHORIZED EQUIPMENT:		IT SUBCONTRACTORS ON-SITE				
	AUTHORIZED PERSONNEL.	- 1	AOTHORIZED EQUI MEITT	POV-					
	RT	•		Van- 1					
	PA			truck- 1					
	Operator			copier- 1					
	Foreman			water cooler- 1					
	Chemist			fax machine- 1					
	Sample Tech	- 1		uniloader- 1					

			Tuesday			
	WORK TO BE PERFORMED:				-	
a	Continue drum sampling and overpacking.	d.				
٠.						
b.	Continue HazCating	e.				
2 3 2 3		•				
U.						
		•				
	AUTHORIZED PERSONNEL:		AUTHORIZED EQUIPMENT:		ar s Jessa	IT SUBCONTRACTORS ON-SITE
٠	RM-	1		POV-	1	
	RT-	4 .		Van-	1 :	
	PA-	1		truck-	1	
	Operator-			copier-	1	
•	Foreman-	1		water cooler-	1	
	Chemist-	1		fax machine- uniloader-	1	
	Sample Tech-	1	Wednesday	uniloadei-	•	
	WORK TO BE PERFORMED:		Vieunosuay			•
a.	Continue drum sampling and overpacking.	d.				
			•			
b.	Continue HazCating.	е.				
		_		•		•
C.		f.				
	AUTHORIZED PERSONNEL:		AUTHORIZED EQUIPMENT:			IT SUBCONTRACTORS ON-SITE
	RM-	1		POV-	1	
	RT-	4		Van-	1	
	PA-	1		truck-	1	
	Operator-			copier-	1	
	Foreman-	1		water cooler-	1	
	T&D Coord:-	1		fax machine-	1	
	Chemist-	1		uniloader-	1 .	
	Sample Tech-	1				

			Thursday				
a.	WORK TO BE PERFORMED: Continue drum sampling and over	rpacking. d.					
b.	Continue HazCating.	e .					
ı	van jaroja kaj jaroja kaj kaj kaj kaj kaj kaj kaj kaj kaj k						
C.	Chageover PA's	f :					
•							
	AUTHORIZED PERSONNEL:		AUTHORIZED EQUIPMENT:		IT SUBC	ONTRACTORS ON-SITE	
		RM- 1		POV-	1		
		RT- 4		Van-	1.		
		PA- 1		truck-	.1)		
		Operator-		copier-	1		
		Foreman- 1		water cooler-	1	•	
		Chemist- 1	•	fax machine-	1	· · · · · · · · · · · · · · · · · · ·	
	S	Sample Tech- 1	·	uniloader-	1,	•	
			Friday (NO WORK)			$e = e^{-\epsilon x} \cdot e^{-\epsilon x} = e^{-\epsilon x}$	
•	WORK TO BE PERFORMED:		•				
a.	Ž.	d.					
L					٠		
b.		e.		-			
C.	· .	f.			· .		
U .			·				
		÷				•	
	AUTHORIZED PERSONNEL:		AUTHORIZED EQUIPMENT:		IT SUBCONTRACTORS ON-SITE		
		RM-	·	POV-			
		RT-	•	Van-			
		PA-		truck-	1		
	•	Operator-		copier-	1		
		Foreman-		water cooler-	1	•	
				fax machine-	1		

uniloader-

Saturday (NO WORK) **WORK TO BE PERFORMED: AUTHORIZED PERSONNEL: AUTHORIZED EQUIPMENT:** RM-RT-PAcopier-Operatorwater cooler-Foremanfax machineuniloader-

IT SUBCONTRACTORS ON-SITE

US EPA OSC Certification:

The personnel, equipment, and tasks detailed above are authorized by the OSC in accordance

with the above referenced delivery order.

On-Scene Coordinator

Date

Acknowledgement of receipt of Weekly Schedule.

IT Representative

Date

POV-Van-

truck-